



CERTIFICATE OF ACCREDITATION

ANSI-ASQ National Accreditation Board

500 Montgomery Street, Suite 625, Alexandria, VA 22314, 877-344-3044

This is to certify that

Gilson, Inc.
3101 Laura Lane, Suite 100
Middleton, WI 53562

has been assessed by ANAB
and meets the requirements of international standard

ISO/IEC 17025:2005

while demonstrating technical competence in the field of

CALIBRATION

Refer to the accompanying Scope of Accreditation for information regarding the types of calibrations to which this accreditation applies.

AC-1731
Certificate Number


ANAB Approval

Certificate Valid: 10/04/2016-09/28/2018
Version No. 004 Issued: 10/04/2016



This laboratory is accredited in accordance with the recognized International Standard ISO/IEC 17025:2005. This accreditation demonstrates technical competence for a defined scope and the operation of a laboratory quality management system (refer to joint ISO-ILAC-IAF Communiqué dated January 2009).



ANSI-ASQ National Accreditation Board

SCOPE OF ACCREDITATION TO ISO/IEC 17025:2005

Gilson, Inc.

3101 Laura Lane, Suite 100, Middleton, WI 53562
Jennifer Leny Phone: 800-445-7661
quality@gilson.com www.pipetman.com

CALIBRATION

Valid to: September 28, 2018

Certificate Number: AC-1731

Mechanical

Parameter/ Equipment	Range	Calibration and Measurement Capability [Expressed as Uncertainty(±)]	Reference Standard or Equipment	Methods
Pipette	(0.2 to 2) µL (2 to 10) µL (10 to 20) µL (20 to 100) µL (100 to 200) µL (200 to 1 000) µL (1 000 to 5 000) µL (5 000 to 10 000) µL	0.007 6 µL 0.009 µL 0.013 µL 0.14 µL 0.14 µL 0.22 µL 0.56 µL 1.2 µL	Mettler Toledo or Sartorius Micro Balance	ISO 8655-6 Gilson Verification Procedure

Notes:

1. Calibration and Measurement Capabilities (Expanded Uncertainty) are based on approximately a 95% confidence interval, using a coverage of $k=2$
2. This laboratory's capabilities include laboratory and on-site calibration services. Since field (on-site) conditions are typically more variable than those in the laboratory, larger measurement uncertainties are expected in the field (on-site) than what is reported on the scope of accreditation.
3. This scope is part of and must be included with the Certificate of Accreditation No.AC-1731.



Vice President

